





TECHNICAL SERVICE BULLETIN



TSB D-MS-0038

Date: October 25, 2022
To: Internal, Sales, Distribution, and Sales Representatives
From: Technical Services Department
Subject: Refrigerant Factory Charge on Data Label for RMXS48LVJU

We have had reports of improperly labeled refrigerant charge on the RMXS48LVJU system. Affected models were produced between 9/5/2018 and 1/13/2022 (end of production). This is a label error only, the charge calculation in the installation manual and Daikin *Split Xpress* remains unaffected.

Incorrect Factory Charge 4 LBS (8.8 kg)	Correct Factory Charge 8.8 LBS (4 kg)
	

All installations of this system will require an additional charge calculation; installers and servicers should refer to the installation manual, charging sticker on the inside panel or the Daikin *Split Xpress* App for the proper factory charge and additional refrigerant charge calculation. It is also recommended to write the total calculated charge down on the inside of the panel where additional refrigerant charge information is listed for future service reference.

Note: This Sales Bulletin constitutes "Confidential Information" as defined in, and is subject to the terms of, your Distributor Sales Agreement.