



## TECHNICAL SERVICE BULLETIN

**TSB-C-GN-SP-0033**

**Date:** July 11, 2023

**To:** All Service and Parts Managers

**From:** Technical Services Department

**Subject: Ceiling Mount Air Handlers (ACSF) Missing Flowrator Tubes**

It has come to our attention that ceiling mount air handlers (ACSF) are missing the Flowrator tube, **Part Number B1796630**, from the literature assembly. ACSF ceiling mount air handlers produced **prior to serial number 2306724252** were shipped without the Flowrator tube. Contractors with units listed below, with serial numbers prior to 2306724252, must obtain Flowrator tubes from their local distributor. Distributors must order Flowrator tube part #B1796630 from Order Services and provide it to their contractors at no cost.

Model	Rev	Model	Rev
ACSF18MN1605	AB	ACSF24LN1610	AB
ACSF18MN1608	AB	ACSF30LN1605	AB
ACSF24LN1605	AB	ACSF30LN1606	AB
ACSF24LN1606	AB	ACSF30LN1608	AB
ACSF24LN1608	AB	ACSF30LN1610	AB

DAIKIN COMFORT TECHNOLOGIES NORTH AMERICA, INC.

19001 Kermier Road • Waller, TX 77484 • (713) 861-2500 • [www.northamerica-daikin.com](http://www.northamerica-daikin.com)

Daikin products are subject to continuous improvements. Daikin reserves the right to modify information in the bulletin without notice and without incurring any obligations.

Amana® is a registered trademark of Maytag Corporation or its related companies and is used under license. All rights reserved.