



## TECHNICAL SERVICE BULLETIN

**TSB C-FN-0046**

**Date:** March 18<sup>th</sup>, 2024


**To:** All Service and Parts Managers

**From:** Technical Services Department


**Subject:** Condensate Management Options for 90%+ AFUE Furnaces

We are providing information regarding condensate management for flue vent and intake piping on 90%+ AFUE condensing furnaces. For furnace installations with long runs of minimally sloped horizontal exhaust pipe, it is important to take the following precautionary steps to help ensure excessive condensate does not flow into the inducer housing or leak out of the assembly into the vestibule compartment.

1. Verify exhaust pipe is sloped no less than  $\frac{1}{4}$  inch per foot.
2. Ensure drain coupling is positioned on the flue pipe adapter so the lower drain port is vertical and not sloped left or right.
3. Verify clamps within drain coupling assembly are properly positioned and tightened according to Figure 1 below.



**Figure 1**



**Figure 2: RF000142 Coupling**

DAIKIN COMFORT TECHNOLOGIES NORTH AMERICA, INC.

19001 Kermier Road • Waller, TX 77484 • (713) 861-2500 • [www.northamerica-daikin.com](http://www.northamerica-daikin.com)

Daikin products are subject to continuous improvements. Daikin reserves the right to modify information in the bulletin without notice and without incurring any obligations.

Amana® is a registered trademark of Maytag Corporation or its related companies and is used under license. All rights reserved.

*(Continued on next page)*



Air Conditioning & Heating



## TECHNICAL SERVICE BULLETIN

If condensate issues persist, the RF000142 coupling, as shown in Figure 2 on previous page, can be installed on the flue vent and/or intake pipe. If the RF000142 coupling is installed on flue vent and/or intake pipe, the arrow on the coupling must be pointing up or against the flow of water for proper drainage. A field supplied "T," as shown in Figure 3, or a field supplied "Y," as shown in Figure 4, installed in the flue vent and/or intake pipe is also an acceptable method of condensate management. Installation of a field supplied "T" or "Y" must include a drain trap and a proper condensate disposal location. If the furnace environment has the potential of freezing, the drain trap and drain line must be protected. The use of accessory drain trap heaters, electric heat tape and/or RV antifreeze is recommended for these installations.




Figure 3




Figure 4

If you have technical questions, please call 1-855-DAIKIN1, option 3, or e-mail  
[TechnicalServicesDaikin@daikincomfort.com](mailto:TechnicalServicesDaikin@daikincomfort.com).

---

---

---

DAIKIN COMFORT TECHNOLOGIES NORTH AMERICA, INC.

19001 Kermier Road • Waller, TX 77484 • (713) 861-2500 • [www.northamerica-daikin.com](http://www.northamerica-daikin.com)

Daikin products are subject to continuous improvements. Daikin reserves the right to modify information in the bulletin without notice and without incurring any obligations.

Amana® is a registered trademark of Maytag Corporation or its related companies and is used under license. All rights reserved.